

~~9/3/2010~~
~~TRC~~

5/2/12
~~10/27/11~~
TRC

4/25/2011
MCC

Cell 37 Cell 54

trans. Cell 37

Cell 37
0 - 50 ft

Diamond grinding blew out sealant in Outside Lane

86+24

86+74

JT 1034


JT 1035

JT 1036

JT 1037

JT 1038

0' 10' 20' 30' 40' 50'



Cell 37
50 - 100 ft

* new sealant in OWP, OL
about 5' in from shld.
(not whole lane)
most jts

86+74


87+24

JT 1039

JT 1040

JT 1041

JT 1042



Cell 37
100 - 150 ft

87+24


87+74

JT 1043

JT 1044

JT 1045

JT 1046



Cell 37
150 - 200 ft

87+74


88+24

JT 1047

JT 1048

JT 1049

JT 1050



Cell 37

200 - 250 ft

88+24

88+74


JT 1051

JT 1052

JT 1053

JT 1054

0' 10' 20' 30' 40' 50'



Cell 37
250 - 300 ft

88+74


89+24

JT 1055

JT 1056

JT 1057

JT 1058



Cell 37
300 - 350 ft

89+24

89+74

JT 1059


JT 1060

JT 1061

JT 1062

JT 1063

0' 10' 20' 30' 40' 50'



Cell 37
350 - 400 ft

89+74


90+24

JT 1064

JT 1065

JT 1066

JT 1067



Cell 37
400 - 450 ft

90+24


90+74

JT 1068

JT 1069

JT 1070

JT 1071



Cell 37
450 - 500 ft

90+74


91+24

JT 1072

JT 1073

JT 1074

JT 1075



Cell 37
500 - 550 ft

Cell 37 Transition

91+24

91+74

JT 1076

JT 1077

JT 1078

JT 1079

