

File LV22

9/27/2013 BAT
(previous Survey 10/5/2012)

Cell 38
0 - 50 ft

Transition Cell 38




JT 1079

JT 1080


JT 1081

JT 1082



TRANSVERSE JOINTS
AT ANGLE

Cell 38
50 - 100 ft



Cell 38
100 - 150 ft


2 + 1087

Panel S

JT 1086

JT 1087

JT 1088



Panel S

CANISTER
dows

4

3

[illegible][illegible]

www.fishbase.org

JT 1095



Cell 38
250 - 300 ft

JT
1099

LI

JT 1098


LI

JT 1097

LI

JT 1096

LI



Centerline is not sealed
these panels 1" width

need to review
when dry

MISSING

MISSING

CANISTER DOWELS


[illegible]

Spill
up station
w/ food tray


7

Cell 38
350 - 400 ft

Panel 24



Cell 38
400 - 450 ft




P. 25

26

27

9

Cell 38
450 - 500 ft



P28

29

48

10

Cell 38
500 - 550 ft

Cell 38 Transition

JT 1113

JT 1114

