

9/24/13 BAT

Previous Survey 10/2/12

File ML07

1131 + 60.8

P-0

Joint 4269

P-1

Joint 4270

CELLS 306-406
0 - 50 Feet

P-2

unsealed joints


Joint 4271

1132 + 00

P-3

1132 + 10.8

10/24/2014 BAT



1132 + 60.8

CELL 306
50 - 100 Feet

P-6

P-5


P-4

Joint 4272

Joint 4273

Joint 4274

Joint 4275



1132 + 10.8

1133 + 10.8

P-10

Joint-4278

1133 + 00

P-9

CELL 306
100 - 150 Feet


Joint-4277

P-8

Joint-4276

P-7

1132 + 60.8



1133 + 60.8

P-13

FWD
13

Joint 4281

CELL 306

150 - 200 Feet

P-12


Joint 4280

P-11

Joint 4279

P-10

1133 + 10.8



1133 + 60.8

Joint 4282

P-14

CELL 306

200 - 250 Feet

P-15

Joint 4283


Joint 4284

P-16

1134 + 00

Joint 4285

1134 + 10.8



1134+60.8

P-2

Joint 4283

P-1

Joint 4287

CELLS 306-406
250 - 300 Feet

P-0


Begin Cell 406 1134 + 22.4

End Cell 306 1134 +

Joint 4286

P-17

1134+10.8



FWD
P. 2

Cell 306 ← | → Cell 406

1/2

1135+10.8

P-5

1135+00

Joint 4251

CELL 406
300 - 350 Feet

P-4


Joint 4250

P-3

Joint 4253

P-2

1134+60.8



1135 + 60.8

Joint-4255

P-8

Joint-4254

CELL 406

350 - 400 Feet


P-7

Joint-4253

P-6

Joint-4252

1135 + 10.8



P.6

1136+10.8

P-12

Joint-4298

1136+00

P-11

Joint-4297


CELL 406
400 - 450 Feet

P-10

Joint-4296

P-9

1135+60.8



1136+60.8

P-15

Joint-4301

CELL 406
450 - 500 Feet

P-14


Joint-4300

P-13

Joint-4299

P-12

1136+10.8



P 13

5

1137 + 10.8

Joint 4305

P-18

1137 + 00

Joint 4304

CELL 406
500 - 550 Feet


P-17

Joint 4303

P-16

Joint 4302

1136 + 60.8



6

CELL 406
550 - 600 Feet

Begin Cell 7 1137 + 14

End Cell 406 1137 + 14

Joint 4305

1137 + 10.8