

note - cell ship sealed on 7/16/2014.


File ML26

BLB-5-12-2015
Snow Plow Scarpa caused loss of chip seal
midlane 4'-6'-
0-50 ft

CELL 19
0 - 50 ft

10/2/2025
3/11/25
LEP


1218+05



CELL 19
100 - 150 ft

1218+55


1219+05



CELL 19
200 - 250 ft

MID-LANE SNOW PLOD DAMAGE
TO CHIP SEAL (POURISH)
RUNING

1220+00




1219+55

1220+05

CELL 19
300 - 350 ft

1220+55

1221+05



1221+55

1222+05

CELL 19
400 - 450 ft

THIS CRACKING IS NOT
NEARLY AS EVIDENT AS
IT WAS LAST FALL

