


3/20/19 LCR



Station
1212+35

N

Cell 18, 50 Feet - 100 Feet

HMA Cracking Study

10-Foot Shoulder

0' 10' 20' 30' 40' 50'



4-Foot Shoulder

Station
1212+85

N

Cell 18, 100 Feet - 150 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'

20'

30'

40'

50'



4-Foot Shoulder

Station
1213+35


N

Cell 18, 150 Feet - 200 Feet

HMA Cracking Study

10-Foot Shoulder

0' 10' 20' 30' 40' 5'



4-Foot Shoulder

Station
1213+85

Cell 18, 200 Feet - 250 Feet

HMA Cracking Study

10-Foot Shoulder

4-Foot Shoulder

Station
1214+35

N



Cell 18, 250 Feet - 300 Feet

HMA Cracking Study

10-Foot Shoulder

0' 10' 20' 30' 40' 50'



4-Foot Shoulder

Station
1214+85

N

Cell 18, 300 Feet - 350 Feet

HMA Cracking Study

10-Foot Shoulder

0' 10' 20' 30' 40' 50'



4-Foot Shoulder

Station
1215+35

N

Cell 18, 350 Feet - 400 Feet

HMA Cracking Study

10-Foot Shoulder

0' 10' 20' 30' 40' 50'



4-Foot Shoulder

Station
1215+85

N

Cell 18, 400 Feet - 450 Feet

HMA Cracking Study

10-Foot Shoulder

0' 10' 20' 30' 40' 50'



4-Foot Shoulder

Station
1216+35

Cell 18, 450 Feet - 500 Feet

HMA Cracking Study

End Station is
1216+85

10-Foot Shoulder

4-Foot Shoulder