

5/4/2018 LCB

210 ft

Beginning Station is
1122+00

Cell 994, 0 Feet - 50 Feet (Transition)
HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]

100'

90'

80'

70'

60'

50'

J-1

J-2

10-Foot Shoulder

Transition

Station
1121+50

Cell 994, 50 Feet - 100 Feet

HMA Overlay Study [1.5-Inch (9.5mm) HMA Wear]

50'

40'

30'

20'

10'

3-Foot Shoulder

00'

J-3


J-4

10-Foot Shoulder

Station is
1121+00

Cell 994, 100 Feet-150 Feet

HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]




10-Foot Shoulder

Station
1120+50

Cell 994, 150 Feet - 200 Feet


HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]



Station is
1120+00

Cell 994, 200 Feet - 250 Feet

HMA Overlay Study [1.5-Inch (9.5mm) HMA Wear]




10-Foot Shoulder

Station
1119+50

Cell 994, 250 Feet - 300 Feet


HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]



Station is
1119+00

Cell 994, 300 Feet - 350 Feet


HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]



Station
1118+50

Cell 994, 350 Feet - 400 Feet


HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]



10-Foot Shoulder

Station is
1118+00


Cell 994, 400 Feet - 450 Feet
HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]



Station
1117+50

Cell 994, 450 Feet - 500 Feet


HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]



Station is
1117+00

Cell 994, 500 Feet - 550 Feet

HMA Overlay Study [1.5-Inch (9.5mm) HMA Wear]




Station
1116+50

Cell 994, 550 Feet - 600 Feet (Transition)

End Station is
1116+00

HMA Overlay Study [1.5-inch (9.5mm) HMA Wear]

50' 40' 30' 20' 10' 3-Foot Shoulder 00'



Transition

10-Foot Shoulder