

LTPP SPS Project Deviation Report Project Summary Sheet		State Code	<u>0 6</u>
		Project Code	<u>A 8 0 0</u>
Project Classification Information			
SPS Experiment Number:	8	State or Province:	California
LTPP Region:	<input type="checkbox"/> North Atlantic <input type="checkbox"/> North Central <input type="checkbox"/> Southern <input checked="" type="checkbox"/> Western		
Climate Zone:	<input type="checkbox"/> Dry-Freeze <input checked="" type="checkbox"/> Dry-No Freeze <input type="checkbox"/> Wet-Freeze <input type="checkbox"/> Wet-No Freeze		
Subgrade Classification:	<input checked="" type="checkbox"/> Fine Grain <input type="checkbox"/> Coarse Grain <input type="checkbox"/> Active (SPS-8 Only)		
Project Experiment Classification Designation (SPS 1, 2 and 8):	23		
Construction Start Date:	May 1999	Construction End Date:	September 1999
Deviation Summary			
Site Location Deviations:	<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations		
Construction Deviations:	<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations		
Data Collection and Processing Status Summary			
Inventory Data (SPS 5,6,7,9):	<input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input checked="" type="checkbox"/> N/A		
Materials Data:	<input checked="" type="checkbox"/> All Scheduled Samples Obtained and Tested <input type="checkbox"/> Incomplete/No Test Data		
Construction Data:	<input type="checkbox"/> All Required Data Obtained <input checked="" type="checkbox"/> Incomplete/Missing Data Elements		
Historical Traffic Data:	<input type="checkbox"/> All Required Historical Estimates Submitted (SPS 5,6,7,9) <input type="checkbox"/> Required Estimates Not Submitted <input checked="" type="checkbox"/> N/A		
Traffic Monitoring Equipment:	<input type="checkbox"/> WIM Installed On-Site <input type="checkbox"/> AVC Installed On-Site <input type="checkbox"/> ATR Installed On-Site <input checked="" type="checkbox"/> No Equipment Installed		
Traffic Monitoring:	<input type="checkbox"/> Preferred <input type="checkbox"/> Continuous <input type="checkbox"/> Minimum <input type="checkbox"/> Below Minimum <input checked="" type="checkbox"/> Site Related		
Traffic Monitoring Data:	<input type="checkbox"/> Monitoring Data Submitted <input checked="" type="checkbox"/> No Monitoring Data Submitted		
FWD Measurements:	<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Construction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed		
Profile Measurements:	<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed		
Distress Measurements:	<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed		
Maint. & Rehab. Data:	<input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input checked="" type="checkbox"/> N/A		
Report Status			
Materials Sampling and Test Plan:	<input type="checkbox"/> Document Prepared <input checked="" type="checkbox"/> Final Submitted to FHWA		
Construction Report:	<input type="checkbox"/> Document Prepared <input type="checkbox"/> Final Submitted to FHWA		
AWS (SPS 1,2,&8):	<input checked="" type="checkbox"/> AWS Installed <input checked="" type="checkbox"/> AWS Installation Report Submitted to FHWA <input type="checkbox"/> N/A		

LTPP SPS Project Deviation Report Project Summary Sheet		State Code	<u>0</u> <u>6</u>
		Project Code	<u>A</u> <u>8</u> <u>0</u> <u>0</u>
Project Classification Information			
SPS Experiment Number:	8	State or Province:	California
LTPP Region:	<input type="checkbox"/> North Atlantic <input type="checkbox"/> North Central <input type="checkbox"/> Southern <input checked="" type="checkbox"/> Western		
Climate Zone:	<input type="checkbox"/> Dry-Freeze <input checked="" type="checkbox"/> Dry-No Freeze <input type="checkbox"/> Wet-Freeze <input type="checkbox"/> Wet-No Freeze		
Subgrade Classification:	<input checked="" type="checkbox"/> Fine Grain <input type="checkbox"/> Coarse Grain <input type="checkbox"/> Active (SPS-8 Only)		
Project Experiment Classification Designation (SPS 1, 2 and 8):	23		
Construction Start Date:	May 1999	Construction End Date:	September 1999
Deviation Summary			
Site Location Deviations:	<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations		
Construction Deviations:	<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations		
Data Collection and Processing Status Summary			
Inventory Data (SPS 5,6,7,9):	<input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input checked="" type="checkbox"/> N/A		
Materials Data:	<input checked="" type="checkbox"/> All Scheduled Samples Obtained and Tested <input type="checkbox"/> Incomplete/No Test Data		
Construction Data:	<input type="checkbox"/> All Required Data Obtained <input checked="" type="checkbox"/> Incomplete/Missing Data Elements		
Historical Traffic Data:	<input type="checkbox"/> All Required Historical Estimates Submitted (SPS 5,6,7,9) <input type="checkbox"/> Required Estimates Not Submitted <input checked="" type="checkbox"/> N/A		
Traffic Monitoring Equipment:	<input type="checkbox"/> WIM Installed On-Site <input type="checkbox"/> AVC Installed On-Site <input type="checkbox"/> ATR Installed On-Site <input checked="" type="checkbox"/> No Equipment Installed		
Traffic Monitoring:	<input type="checkbox"/> Preferred <input type="checkbox"/> Continuous <input type="checkbox"/> Minimum <input type="checkbox"/> Below Minimum <input checked="" type="checkbox"/> Site Related		
Traffic Monitoring Data:	<input type="checkbox"/> Monitoring Data Submitted <input checked="" type="checkbox"/> No Monitoring Data Submitted		
FWD Measurements:	<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Construction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed		
Profile Measurements:	<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed		
Distress Measurements:	<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed		
Maint. & Rehab. Data:	<input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input checked="" type="checkbox"/> N/A		
Report Status			
Materials Sampling and Test Plan:	<input checked="" type="checkbox"/> Document Prepared <input checked="" type="checkbox"/> Final Submitted to FHWA		
Construction Report:	<input type="checkbox"/> Document Prepared <input type="checkbox"/> Final Submitted to FHWA		
AWS (SPS 1,2,&8):	<input checked="" type="checkbox"/> AWS Installed <input checked="" type="checkbox"/> AWS Installation Report Submitted to FHWA <input type="checkbox"/> N/A		

LTPP SPS Project Deviation Report Data Collection and Materials Sampling and Testing Deviations	State Code <u>06</u> Project Code <u>A 8 0 0</u>
----------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------

Comments Pertain to All Test Sections on Project
 Comments Pertain Only to Section(s): (Specify) 06A805, 06A806

Data Collection & Material Sampling and Testing Deviation Comments:

- Section 06A805 - Shoulder auger probe drilling was not performed for this section because of the presence of overhead power lines. Caltrans has expressed their inability to perform shoulder probe drilling on this particular section.
- Section 06A806 - Shoulder auger probe drilling was performed at the beginning of test section (section station 0+00) instead of the mid point of test section (section station 76+0).

