

LTPP SPS Project Deviation Report	State Code	<u>2</u>	<u>7</u>	
Project Summary Sheet	Project Code	<u>0</u>	<u>9</u>	<u>0</u> <u>0</u>
Project-Classification Information				
SPS Experiment Number: SPS-9		State or Province: Minnesota		
LTPP Region:	<input type="checkbox"/> North Atlantic	<input checked="" type="checkbox"/> North Central	<input type="checkbox"/> Southern	<input type="checkbox"/> Western
Climate Zone:	<input checked="" type="checkbox"/> Dry Freeze	<input type="checkbox"/> Dry-No Freeze	<input type="checkbox"/> Wet-Freeze	<input type="checkbox"/> Wet-No Freeze
Subgrade Classification:	<input checked="" type="checkbox"/> Fine Grain	<input type="checkbox"/> Coarse Grain	? <input type="checkbox"/> Active (SPS-8 Only)	
Project Experiment Classification Designation (SPS 1, 2 and 8): NA				
Construction Start Date: July, 1993		Construction End Date: August, 1993		
FHWA Incentive Funds Provided to Agency for this Project:				<input type="checkbox"/> Yes <input type="checkbox"/> No
Deviation Summary				
Site Location Deviations:	<input checked="" type="checkbox"/> No Deviations	<input type="checkbox"/> Minor Deviations	<input type="checkbox"/> Significant Deviations	
Construction Deviations:	<input type="checkbox"/> No Deviations	<input checked="" type="checkbox"/> Minor Deviations	<input type="checkbox"/> Significant Deviations	
Data Collection and Processing Status Summary				
Inventory Data (SPS 5, 6, 7, 9):	<input checked="" type="checkbox"/> Complete Submission	<input type="checkbox"/> Incomplete	<input type="checkbox"/> Data Not Available	
Materials Data:	<input checked="" type="checkbox"/> All Scheduled Samples Obtained and Tested		<input type="checkbox"/> Incomplete	
Construction Data:	<input checked="" type="checkbox"/> All Required Data Obtained		<input type="checkbox"/> Incomplete/Missing Data Elements	
Historical Traffic Data:	<input checked="" type="checkbox"/> All Required Historical Estimates Submitted (SPS 5, 6, 7, 9)			
	<input type="checkbox"/> Required Estimates Not Submitted			
Traffic Monitoring Equipment:	<input checked="" type="checkbox"/> WIM Installed On-Site	<input type="checkbox"/> AVC Installed On-Site		
	<input type="checkbox"/> ATR Installed On-Site	<input type="checkbox"/> No Equipment Installed		
Traffic Monitoring:	<input type="checkbox"/> Preferred	<input type="checkbox"/> Continuous	<input type="checkbox"/> Minimum	<input checked="" type="checkbox"/> Below Minimum <input type="checkbox"/> Site Related
Traffic Monitoring Data:	<input type="checkbox"/> Monitoring Data Submitted		<input checked="" type="checkbox"/> No Monitoring Data Submitted	
FWD Measurements:	<input checked="" type="checkbox"/> Preconstruction Tests Performed		<input checked="" type="checkbox"/> Construction Tests Performed	
	<input checked="" type="checkbox"/> Post-construction Tests Performed			
Profile Measurements:	<input type="checkbox"/> Preconstruction Tests Performed		<input checked="" type="checkbox"/> Post-construction Tests Performed	
Distress Measurements:	<input checked="" type="checkbox"/> Preconstruction Tests Performed		<input checked="" type="checkbox"/> Post-construction Tests Performed	
Maint. & Rehab. Data:	<input checked="" type="checkbox"/> Complete Submission		<input type="checkbox"/> Incomplete	<input type="checkbox"/> Data Not Available
Friction Data:	<input type="checkbox"/> Complete Submission		<input type="checkbox"/> Incomplete	<input checked="" type="checkbox"/> Data Not Available
Report Status				
Materials Sampling and Test Plan:	<input checked="" type="checkbox"/> Document Prepared		<input type="checkbox"/> Final Submitted to FHWA	
Construction Report:	<input checked="" type="checkbox"/> Document Prepared		<input checked="" type="checkbox"/> Final Submitted to FHWA	
AWS: (SPS 1, 2, & 8) NA	<input type="checkbox"/> AWS Installed	<input type="checkbox"/> AWS Installation Report Submitted to FHWA		

LTPP SPS Project Deviation Report

State Code

2 7

Data Collection and

Project Code

0 9 0 0

Materials Sampling and Testing Deviations

Comments Pertain to All Test Sections on Project

Comments Pertain Only to Section(s): (Specify)

Data Collection & Material Sampling and Testing Deviation Comments:

None

LTPP SPS Project Deviation Report	State Code <u>2</u> <u>7</u>
Other Deviations	Project Code <u>0</u> <u>9</u> <u>0</u> <u>0</u>

Comments Pertain to All Test Sections on Project

Comments Pertain Only to Section(s): (Specify)

Other Deviation Comments:

Test section 200910 was moved 200 ft. to the south because severely deteriorated concrete that would require additional asphalt thickness was located at the proposed test section location.

The construction report contains only limited information.