

| | | | | | |
|--|--|---|---|--|--|
| LTPP SPS Project Deviation Report | | State Code | | 5 | 5 |
| Project Summary Sheet | | Project Code | | 0 | 9 0 0 |
| Project-Classification Information | | | | | |
| SPS Experiment Number: SPS-9 | | | State or Province: Wisconsin | | |
| LTPP Region: | | <input type="checkbox"/> North Atlantic | <input checked="" type="checkbox"/> North Central | <input type="checkbox"/> Southern | <input type="checkbox"/> Western |
| Climate Zone: | | <input type="checkbox"/> Dry Freeze | <input type="checkbox"/> Dry-No Freeze | <input checked="" type="checkbox"/> Wet-Freeze | <input type="checkbox"/> Wet-No Freeze |
| Subgrade Classification: | | <input type="checkbox"/> Fine Grain | <input checked="" type="checkbox"/> Coarse Grain | ? <input type="checkbox"/> Active (SPS-8 Only) | |
| Project Experiment Classification Designation (SPS 1, 2 and 8): NA | | | | | |
| Construction Start Date: May, 1992 | | | Construction End Date: July, 1992 | | |
| FHWA Incentive Funds Provided to Agency for this Project: | | | | | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| Deviation Summary | | | | | |
| Site Location Deviations: | | <input type="checkbox"/> No Deviations | <input checked="" type="checkbox"/> Minor Deviations | <input type="checkbox"/> Significant Deviations | |
| Construction Deviations: | | <input checked="" type="checkbox"/> No Deviations | <input type="checkbox"/> Minor Deviations | <input type="checkbox"/> Significant Deviations | |
| Data Collection and Processing Status Summary | | | | | |
| Inventory Data (SPS 5, 6, 7, 9): | | <input checked="" type="checkbox"/> Complete Submission | <input type="checkbox"/> Incomplete | <input type="checkbox"/> Data Not Available | |
| Materials Data: | | <input checked="" type="checkbox"/> All Scheduled Samples Obtained and Tested | <input type="checkbox"/> Incomplete | | |
| Construction Data: | | <input checked="" type="checkbox"/> All Required Data Obtained | <input type="checkbox"/> Incomplete/Missing Data Elements | | |
| Historical Traffic Data: | | <input type="checkbox"/> All Required Historical Estimates Submitted (SPS 5, 6, 7, 9) | | | |
| | | <input checked="" type="checkbox"/> Required Estimates Not Submitted | | | |
| Traffic Monitoring Equipment: | | <input checked="" type="checkbox"/> WIM Installed On-Site | <input checked="" type="checkbox"/> AVC Installed On-Site | | |
| | | <input type="checkbox"/> ATR Installed On-Site | <input type="checkbox"/> No Equipment Installed | | |
| Traffic Monitoring: | | <input checked="" type="checkbox"/> Preferred | <input type="checkbox"/> Continuous | <input type="checkbox"/> Minimum | <input type="checkbox"/> Below Minimum <input type="checkbox"/> Site Related |
| Traffic Monitoring Data: | | <input checked="" type="checkbox"/> Monitoring Data Submitted | <input type="checkbox"/> No Monitoring Data Submitted | | |
| FWD Measurements: | | <input type="checkbox"/> Preconstruction Tests Performed | <input checked="" type="checkbox"/> Construction Tests Performed | | |
| | | <input checked="" type="checkbox"/> Post-construction Tests Performed | | | |
| Profile Measurements: | | <input checked="" type="checkbox"/> Preconstruction Tests Performed | <input checked="" type="checkbox"/> Post-construction Tests Performed | | |
| Distress Measurements: | | <input checked="" type="checkbox"/> Preconstruction Tests Performed | <input checked="" type="checkbox"/> Post-construction Tests Performed | | |
| Maint. & Rehab. Data: | | <input checked="" type="checkbox"/> Complete Submission | <input type="checkbox"/> Incomplete | <input type="checkbox"/> Data Not Available | |
| Friction Data: | | <input type="checkbox"/> Complete Submission | <input type="checkbox"/> Incomplete | <input checked="" type="checkbox"/> Data Not Available | |
| Report Status | | | | | |
| Materials Sampling and Test Plan: | | <input checked="" type="checkbox"/> Document Prepared | <input type="checkbox"/> Final Submitted to FHWA | | |
| Construction Report: | | <input checked="" type="checkbox"/> Document Prepared | <input checked="" type="checkbox"/> Final Submitted to FHWA | | |
| AWS: (SPS 1, 2, & 8) NA | | <input checked="" type="checkbox"/> AWS Installed | <input type="checkbox"/> AWS Installation Report Submitted to FHWA | | |

| | | | |
|-------------------------------------|--------------|----------|----------|
| LTPP SPS Project Deviation Report | State Code | <u>5</u> | <u>5</u> |
| Site Location Guidelines Deviations | Project Code | <u>0</u> | <u>9</u> |
| | | <u>0</u> | <u>0</u> |

Comments Pertain to All Test Sections on Project

Comments Pertain Only to Section(s): (Specify)

Site Location Guideline Deviation Comments:

Horizontal and vertical curves are located within test section project limits.

Some test sections are built on fill areas, others on cut areas of the roadway.

