

| | | | |
|-----------------------------------|--------------|-----|-----|
| LTPP SPS Project Deviation Report | State Code | 5 | 5 |
| Project Summary Sheet | Project Code | A 9 | 0 0 |

Project-Classification Information

| | |
|--|--|
| SPS Experiment Number: SPS-9 | State or Province: Wisconsin |
| LTPP Region: | <input type="checkbox"/> North Atlantic <input checked="" type="checkbox"/> North Central <input type="checkbox"/> Southern <input type="checkbox"/> Western |
| Climate Zone: | <input type="checkbox"/> Dry Freeze <input type="checkbox"/> Dry-No Freeze <input checked="" type="checkbox"/> Wet-Freeze <input type="checkbox"/> Wet-No Freeze |
| Subgrade Classification: | <input type="checkbox"/> Fine Grain <input checked="" type="checkbox"/> Coarse Grain ? <input type="checkbox"/> Active (SPS-8 Only) |
| Project Experiment Classification Designation (SPS 1, 2 and 8): | NA |
| Construction Start Date: July, 1992 | Construction End Date: August, 1992 |
| FHWA Incentive Funds Provided to Agency for this Project: <input type="checkbox"/> Yes <input type="checkbox"/> No | |

Deviation Summary

| | |
|---------------------------|---|
| Site Location Deviations: | <input checked="" type="checkbox"/> No Deviations <input type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations |
| Construction Deviations: | <input checked="" type="checkbox"/> No Deviations <input type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations |

Data Collection and Processing Status Summary

| | |
|----------------------------------|---|
| Inventory Data (SPS 5, 6, 7, 9): | <input checked="" type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available |
| Materials Data: | <input checked="" type="checkbox"/> All Scheduled Samples Obtained and Tested <input type="checkbox"/> Incomplete |
| Construction Data: | <input checked="" type="checkbox"/> All Required Data Obtained <input type="checkbox"/> Incomplete/Missing Data Elements |
| Historical Traffic Data: | <input type="checkbox"/> All Required Historical Estimates Submitted (SPS 5, 6, 7, 9) <input checked="" type="checkbox"/> Required Estimates Not Submitted |
| Traffic Monitoring Equipment: | <input checked="" type="checkbox"/> WIM Installed On-Site <input checked="" type="checkbox"/> AVC Installed On-Site <input type="checkbox"/> ATR Installed On-Site <input type="checkbox"/> No Equipment Installed |
| Traffic Monitoring: | <input checked="" type="checkbox"/> Preferred <input type="checkbox"/> Continuous <input type="checkbox"/> Minimum <input type="checkbox"/> Below Minimum <input type="checkbox"/> Site Related |
| Traffic Monitoring Data: | <input checked="" type="checkbox"/> Monitoring Data Submitted <input type="checkbox"/> No Monitoring Data Submitted |
| FWD Measurements: | <input checked="" type="checkbox"/> Preconstruction Tests Performed <input type="checkbox"/> Construction Tests Performed <input checked="" type="checkbox"/> Post-construction Tests Performed |
| Profile Measurements: | <input checked="" type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-construction Tests Performed |
| Distress Measurements: | <input checked="" type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-construction Tests Performed |
| Maint. & Rehab. Data: | <input checked="" type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available |
| Friction Data: | <input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input checked="" type="checkbox"/> Data Not Available |

Report Status

| | |
|-----------------------------------|---|
| Materials Sampling and Test Plan: | <input checked="" type="checkbox"/> Document Prepared <input type="checkbox"/> Final Submitted to FHWA |
| Construction Report: | <input checked="" type="checkbox"/> Document Prepared <input checked="" type="checkbox"/> Final Submitted to FHWA |
| AWS: (SPS 1, 2, & 8) NA | <input type="checkbox"/> AWS Installed <input type="checkbox"/> AWS Installation Report Submitted to FHWA |

LTPP SPS Project Deviation Report

State Code 5 5

Site Location Guidelines Deviations

Project Code A 9 0 0

Comments Pertain to All Test Sections on Project

Comments Pertain Only to Section(s): (Specify)

Site Location Guideline Deviation Comments:

None

