



IRD PAT Traffic

Site Service Sheet

Clear

Kistler

System Type: iSinc

Date: 5/20/2011
Job #: 11167

State: DeLTPP
Site #: _____

Location: Georgetown, DE
Directions: RT 113- 3 miles south of rt 16

	SBDr1	SBDr2						
Loops	Lane - 4							
Resistance	1.5	1.6						
Leakage								
Shield	150.0	240.0						
Inductance(uh)	209.0	253.0						

	Rt	Lt						
Piezos	Lane -							
Amplitude								
Capacitance(nf)	14.9	ol						
Resistance	ol	8.0						

	Length -							
Piezos	Lane -							
Amplitude								
Capacitance								
Resistance								

System

A/C Service	121.0
Power Supply	
Solar Panel	
Back-Up	13.6
System Input	
Modem Power	
Phone off	
Phone on	

Temp Sensor

White+	
Red +	

Software

System	
Loop	
Piezo	

Site Full Operating Capacity

Pass

Fail X Trailing kistler has failed. Had to zap K1 with 12v to restore it's reac

Technician: Steven Schroeder Date: 5/20/11

lings.