



**INTERNATIONAL ROAD DYNAMICS INC.**

224-176 W. Logan St. Noblesville In, 46060

☎ 317-502-1845 Fax: 240-337-8573

**- Site Service Report -**

Date: June 9, 2009

**IRD SO.: 10785A**

**IRD Contract No.:**

**From: Travis Holton**

**To: ESS**

**State: Illinois**

**Project Name/Location: I-57 Tuscola NB**

**Service Date(s): March 29, 2006**

**Job Description: Perform spring site check and replace scale card.**

**Work Completed:**

- I replaced the old scale card and installed a new scale card with improved firmware and modified the calibration factors to suit the new card
- I checked the operation and verified that the vehicle records looked proper
- I completed the electrical readings report for all the electrical components on site
- I shortened the ground leads to the sensor interface cards as Bruce had requested
- I cleaned out the cabinet to remove dirt and dust
- I photographed and checked the road installation
- The road installation was in excellent condition with no major cracking

**Work Remaining: None.**

**Parts Used: Scale Interface Card PN: 195210**

**Mileage : 320 miles.**

**Hours Worked : 5 hours driving, 4 hours onsite. Total 9 hours.**

**Notes:**

**Action Items:**

| Item | Action Required | Ownership |
|------|-----------------|-----------|
| 1.   |                 |           |
| 2.   |                 |           |
| 3.   |                 |           |
| 4.   |                 |           |