



INTERNATIONAL ROAD DYNAMICS INC.
 702-43rd Street East Saskatoon, SK CANADA S7K 3T9
 Phone: (306) 653-6600 Fax: (306) 242-5599 Email: info@irdinc.com
 VISIT IRD ON THE WEB <http://www.irdinc.com>

Maintenance Report

	Maine LTPP Site
Site Number: LTPP ME1	
Service Date(s):	10/28 /2010
IRD S/O, Contract No.:	S.O.# 11167
Service Performed By :	JSM

Loops :

Sensor #	Resistance Ω	Resistance to Shield	Megger Resistance MΩ	Inductance μH	Comments: DO NOT SET MEGGER ABOVE 500V RESPLICE BELOW 20MΩ
Loop 1:	1.780	OL	1190	136.0	
Loop 2:	1.781	OL	OL	136.8	

Kistler :

Sensor #	Resistance Ω	Capacitance nF	Dissipation	Car Peak Voltage	Semi Peak Voltage	Comments Grout condition, Waveform
<u>Kistler 1:</u>	OL	10.963	.007	600mv	1V	Good Condition
<u>Kistler 2:</u>	OL	10.719	.004			Good Condition
<u>Kistler 3:</u>	OL	11.672	.011	600mv	1V	Good Condition
<u>Kistler 4:</u>	OL	10.879	.004			Good Condition