



INTERNATIONAL ROAD DYNAMICS INC.

702 43rd Street East, Saskatoon SK Canada

☎ 317-694-4224

- Site Service Report -

IRD SO.: 11167

IRD Contract No.:

From: Steve Schroeder

State: Maryland

Project Name/Location: Rt 15 Frederick, Md

Service Date(s): 2-7-11

Job Description: Perform annual site inspection.

Work Completed: Drove to site. Performed visual inspection of sensors. Grout looks good. Sensors look good. Performed Electrical check. Found Loop one has a low shield resistance. Phone line was dead. Cindy Mantie was made aware. Otherwise site looks good. Bruce dialed in and verified operation on cell modem.

Work Remaining: None

Parts Used:

Part Name	Part Number	Quantity Used

Mileage : 295 miles

Hours Worked: 5 hours

Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		