

**- Site Service Report -**

Date: June 9, 2009

IRD SO.: 10785G

IRD Contract No.: 10785G

From: John Folkerts

To: ESS

State: Illinois

Project Name/Location: Bemidji – Highway 2

Service Date(s): June 6, 2007

Job Description: Site inspection needs to be performed.

**Work Completed:**

- Noticed that all kistler soldier sleeves had been crimped and not soldered.
- Re-terminated all kistlers.
- Noticed that all loops had bad terminations done.
- Re-terminated all loops.
- Measured and recorded data for all sensors.
- Re-spliced loop 6.
- All sensors have very good measurements.
- Took pictures of all kistlers, loops, and cabinet.

Work Remaining: None.

Parts Used: None.

Part Name	Part Number	Quantity Used

Mileage: 250 miles.

Hours Worked: 3.5 hours travel, 4.5 hours onsite.

Total: 8 hours.

**Notes:**

**Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		