



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- Site Report -

Date: December 08 2008

IRD Sales Order: 11013

To: Greg Felsing

From: Bryan Knight

Project Name/Location: SPS51 / NM I25N mp 35

Service Date(s): December 08 2008

Job Description: Performed Annual System Health Check.

Work Completed: Measured and Recorded the Inductance, Resistance, and Voltage readings of the in-road sensors (Kistler and Loops). Measured Solar Panel Output and MODEM supply voltage. No discrepancies noted. System is fully functional.

Work Remaining: None

Schedule Include Estimate to Complete (on-track, ahead, behind): N/A

Parts Used: None

Pre-mature Equipment Failure: None Noted

Mileage / Travel Time: Total Travel: 5 hrs. Total Onsite: 3 hrs.

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com



Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		