

## - Site Service Report -

Date: June 9, 2009

IRD SO.: 10407Q

IRD Contract No.:

From: Tim Weber

To: ESS

State: Illinois

Project Name/Location: Wausau SH 29 MM189.8 WB

Service Date(s): September 20, 2007

Job Description: Check to see if power is on at site.

Work Completed:

When we got to site, we noticed that a meter poll had been installed. The power was on on it but not in our cabinet. Same with the phone. John and I went to Home depot and bought some conduit and cable. We installed the new conduit between the cabinet and the new meter poll. We pulled new cable and then connected the power and and phone lines. We turned on the Isinc and it worked. We tested the phone line and it was busy. We will have to get the phone company to check their end of the line.

I set up the parameters in the Isinc. We watched vehicles for a while. Everything looked good.

Work Remaining: The site still needs to be calibrated.

Parts Used: None.

Part Name	Part Number	Quantity Used

Mileage: 300 miles.

Hours Worked: 5 hours Tim and 5 hours John on site.

Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		