



INTERNATIONAL ROAD DYNAMICS INC.

224-176 W. Logan St. Noblesville In, 46060

☎ 317-502-1845 Fax: 240-337-8573

- Site Service Report -

Date: January 10, 2012

IRD SO.: 11378

IRD Contract No.:

From: Tim Weber

To: ESS

State: Wisconsin

Project Name/Location: Hwy 29 Wausau WB

Service Date(s): November 2, 2011

Job Description: Semi-annual site inspection.

Work Completed:

I stopped on site and did a visual inspection of the plates. The bending plates looked good. I tested the loops and bending plates and recorded all of the results. I also megged out the loops and they looked good. I measured the power and phone and recorded the results.

The battery looks good. It measured out at 13.8 VDC.

Work Remaining: None

Parts Used: None

Mileage : 700 miles.

Hours Worked : 10 hours driving, 1 hour onsite

Total: 11 hours