


1245+55

2-1




1245+05

CELL 23

ML10-F-23


DISTRESS SURVEY - OCTOBER 14-22, 1999

DISTRESS SURVEY - OCTOBER 14-22, 1999



1244+55

1244+05




CELL 23

ML10-F-23

DISTRESS SURVEY - OCTOBER 14-22, 1999


DISTRESS SURVEY - OCTOBER 14-22, 1999



1243+55

Handwritten mark

1243+05



CELL 23


ML10F-23

DISTRESS SURVEY - OCTOBER 14-22, 1999

1243+05

1243+00

1242+55



CELL 23

ML10-F-23

DISTRESS SURVEY - OCTOBER 14-22, 1999


1242+55

Handwritten mark

Handwritten mark

Handwritten mark

1242+05




CELL 23

ML10-F-23

DISTRESS SURVEY - OCTOBER 14-22, 1999

INSPECTION


DISTRESS SURVEY - OCTOBER 14-22, 1999



1241+55

Handwritten 'V-L' with a checkmark

1241+05



CELL 23

ML10-F-23

SENSOR AREA

DISTRESS SURVEY - OCTOBER 14-22, 1999

DISTRESS SURVEY - OCTOBER 14-22, 1999

