





CELL 28
LVR-F-12

INSPECTION

DISTRESS SURVEY – OCTOBER 14-22, 1999

185+50


185+00



INSPECTION

185+00

184+50



100'

110'

120'

130'

140'

150'


CELL 28

LVR-F-12

7

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999




CELL 28
LVR-F-12

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999

184+00

183+50



200'

210'

220'

230'

240'

250'

CELL 28


LVR-F-12

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999

183+50

183+00




CELL 28

LVR-F-12


INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999



INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999



CELL 28


LVR-F-12

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999

182+00

181+50



CELL 28


LVR-F-12

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999

181+50

181+00



450'

460'

470'

480'

490'

500'

CELL 28

LVR-F-12

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999