


2.3 - no change
Sealed cracks ok
10/22/01 - no edge cracks
Sealed cracks ok
in good shape

1245+55

S.R.
cell

1245+05



0' Frs

only
change

10'

20'

30'


40'

50'


CELL 23

MI.10-F-23


DISTRESS SURVEY - OCTOBER 22-26, 2001



DISTRESS SURVEY - OCTOBER 22-26, 2001




DISTRESS SURVEY – OCTOBER 22-26, 2001




CELL 23
M105.02


DISTRESS SURVEY – OCTOBER 22-26, 2001




DISTRESS SURVEY – OCTOBER 22-26, 2001




DISTRESS SURVEY – OCTOBER 22-26, 2001




DISTRESS SURVEY – OCTOBER 22-26, 2001



DISTRESS SURVEY – OCTOBER 22-26, 2001



DISTRESS SURVEY – OCTOBER 22-26, 2001



CELL 23

MI 10-F-23

DISTRESS SURVEY – OCTOBER 22-26, 2001