


- * All transverse & long (6') joints sealed L unless otherwise noted
- * CL & both shoulder joints – seal gone

CELL 96

0-50ft

JOINT 2247

JOINT 2237



11/6/07 4/14/08
5/14/07 TRC


beginning to see damage (spoiling)
along its, especially driving lane
- fibers showing

CELL 96

50-100ft

JOINT 2237

JOINT 2227



CELL 96

100-150ft

JOINT 2227

JOINT 2217

100'

110'

120'

JOINT 2222

130'

140'

150'

12'

12

8'

8'

4'

4'

0'

0'

-4'

-4'

-8'

-8'

-12

100'


110'

120'

130'

140'

150'




CELL 96

150-200ft

JOINT 2217

JOINT 2211



evidence of pumping on DL shoulder
- selected joints