

JOINT DAMAGE ALONG ENTIRE DRIVING LANE SHOULDER.

Cell 105

WEST

1125+80

JT 0

0'

10'

JT 1

20'

JT 2

30'

JT 3


40'

1126+30

CELL 5
0 - 50 ft

EAST

East
6/16/09



(Driving)
INSIDE

SL - 35

SH - 1

SM - 1

Passing

SL - 35

SH - 1

SM - 1

(Driving)
INSIDE

SL - 2 (16ft)

Passing

CELL 5
50 - 100 ft

EAST

WEST


1126+80

1126+30

JT 6

JT 5


JT 4



CELL 5
100 - 150 ft

WEST

EAST



WEST

CELL 5
150 - 200 ft

EAST

1127+80


Cell 105 | Cell 205

1127+30

JT 13

JT 12

JT 11



EAST

CELL 5
200 - 250 ft

WEST

1128+30

1127+80

JT 16

JT 15


JT 14

20'

30'

40'


50'



EAST

CELL 5
250 - 300 ft

WEST




EAST

CELL 5
300 - 350 ft


Cell 205 | Cell 305

1129+30



WEST


CELL 5
350 - 400 ft



EAST

CELL 5
400 - 450 ft

WEST




EAST

CELL 5
450 - 500 ft

Cell 305 | Cell 405


1130+80



WEST

EAST

CELL 5
500 - 550 ft



EAST

CELL 5
550 - 600 ft

405/106

Cell 405 | Cell 106

1131+73

1131+30

WEST

