

* No joints sealed

CELL 63

Task 2.

7/23/09
TRC

JOINT 2481

0' 1162+33.80

Passing
SL-45
3A-(6) 10ft
4M-(1) 12ft

Driving 0-50M
SL-45
2M-(2) 5ft
2L-(1) 5ft
3L-(5) 37ft
4M-(1) 4ft
4L-(3) 8ft

* no joint seal during
(mosses)

JOINT 2471

50' 13' 12'



4/16/09
5/14/08
TRC

CRACKS ALL ALONG BOTH SHOULDER

CELL 63

50-100ft

JOINT 2471

50' 1161+85.37

60'

70'

80'

skld crack 90°

JOINT 2461

100'

13' 12

12'

8'

4'

0

-4'

-8'

-12'

1161+84.97

50'

60'

70'

80'

100'

-12


-8'

-4'

0

4'

8'



CELL 63


100-150ft

JOINT 2451

JOINT 2461

100' 1161+35.36

1161+35.36 100'



CELL 63

150-200ft

JOINT 2451

150' 1160+85.32

160'


170'

180'

190' Fractured

JOINT 2441

200'



1160+84.92

150'

160'

170'

180'

190'

200'

Fractured slab

CELL 63

200-250ft

JOINT 2441

200' 1160+35.41

210'

220'

JOINT 2336

230'

240'

250'

12'

8'

4'

0'

-4'

-12'

1160+34.86

200' 2441

210'

220'

230'

240'

250'

-12

-8

-4

0

4

8

12

5' full level
10' 1/2' clamp
exposed 8'
no gaps
needs patch

3 1/2"

5' hld. wait