


CELL 96

150-200ft



evidence of pumping on DL shoulder
- selected joints

* All transverse & long (6') joints
sealed L unless otherwise noted
* CL & both shoulder joints -
seal gone


CELL 96

0-50ft

EXT 12 2
6/16/09

JOINT 2237

JOINT 2247



11/6/07 4/14/08
5/14/09 TRC

beginning to see damage (sprinkling)
along its, especially driving lane
fibers showing

Driving
SL - 60
SM - 8
3L - 11) 64t

Passing
SL - ~~60~~ 62
SM - 6

CELL 96

50-100ft

JOINT 2227

JOINT 2237

50'

60'


70'

JOINT 2232

80'

90'

100'



CELL 96

100-150ft

JOINT 2217

JOINT 2277

JOINT 2222

