


- * All transverse & long (6") joints sealed L unless otherwise noted
- * CL & both shoulder joints - seal gone

CELL 96

0-50ft

JOINT 2247

JOINT 2247




0 7/16/07
5/14/07 TRC 9/16/09

beginning to sand down (spalling)
along rt. especially during hot
fibers showing.

CELL 96

50-100ft



CELL 96

100-150ft

JOINT 1977

JOINT 2217

100'

110'

120'

130'

140'

150'

12'


8'

4'

0'


-4'

-8'



CELL 96

150-200ft



evidence of pumping on DL shoulder
- selected joints