

~~9/24/2011~~
~~mk~~
~~4/25/2011~~
~~mk~~
10/27/11
TRC

CELL 53
0 - 50 ft

-1st panel on east end in both shlds (OL & IL) is cracked

8/16 panels cracked
inside shld JT 3

Cell 53


210+85

JT 0

JT 1

JT 2

211+35



9/16 panels cracked
outside shld

CELL 53
50 - 100 ft


211+35

211+85

JT 4

JT 5

JT 6



CELL 53
100 - 150 ft

Cell 53 | Cell 54

211+35

JT 7

212+00

JT 8

