

4/25/11
MRC

~~4/25/11~~
~~MRC~~

4/27/11
TRC 4/24/12

CELL 53
0 - 50 ft

-1st panel on east end in both shlds (OL & IL) is cracked

Cell 53

210+85


JT 8
30' 10' 12'

JT 8
1267

JT 8
1268

8/16 panels cracked
inside shld JT 8
1269

211+35



9/16 panels cracked
outside shld

1269

105

CELL 53
50 - 100 ft


211+35

211+85

JT 4
1270
10'

JT 3
1271

JT 6
1272
40'



CELL 53
100 - 150 ft

Cell 53 | Cell 54

211+35

JT #
073

