

~~10/27/81~~  
~~10/5/82~~

CELL 53  
0-59 ft

1st panel on east end in both shds (CL & IL) is cracked

211+35

Cell 53  
210+85


JT<sup>8</sup> 1267

0' 10' 20'

12' Inside Lane  
0' 10' 20' 30' 40' 50'  
CL 1269

8/16 panels cracked  
inside shield JT<sup>8</sup>

211+35



9/16 panels cracked  
outside shld

✓ CG ✓

CELL 53  
50'-100' \$

211435

211485

0' JT<sup>4</sup> 1270 20' JT<sup>5</sup> 1271 30' JT<sup>6</sup> 1272 40' 50'

12' Inside Lane 12' Outside Lane

0' 4' 0' 4' 0' 4' 0' 4' CL

10' 20' 30' 40' 50' 12'


CELL 53

100 - 150 ft

Cell 53 | Cell 54

211+85

6273



20'

30'

40'

50'

12'

12'

Inside Lane

CL

O2

4'

8'

12'

Outside Lane

20'

30'

40'

50'

