

9/24/13 BAT

(previous survey 9/24/12)

File ML01

1103+10

CELL 1
0 - 50 ft


5/5/2014 DAT

All FWD points (10-1.5)
are 10 ft too far East

1103+60

Evidence of
settling @ WP
cracks. see pics.


10/21/2014 DAT



CELL 1 50 - 100 ft

1103+60

1104+10




CELL 1
100 - 150 ft

Peeling of wire mesh

STRAWING


STRAWING




CELL 1 150 - 200 ft

1104+60


1105+10



CELL 1
200 - 250 ft



CELL 1
250 - 300 ft



✓

micro peetes off


30'



CELL 1
350 - 400 ft

1106+60


1107+10



Corr of 4' crack

5/5/2014 OASV

CELL 1
400 - 450 ft



CELL 1
450 - 500 ft

1107+60

1108+10

