

4/2/2014 DAV

9/24/2013 BAT

(previous survey 9/24/2012)


CELL 21
0-50 ft

note: w/p creaking was observed
These are not very cracks
but look very fatigue like.
They are very fine cracks.

10/27/2014 DAV

1228+95

1229+45




STAINING on short transverse cracks
in OR over.

1/10

CELL 21
50 - 100 ft

1229+45

1229+95




2/10

CELL 21
100 - 150 ft

1229+95

1230+45




3/10

CELL 21
150 - 200 ft

1230+45

1230+95




4/10

CELL 21
200 - 250 ft

1230+95

1231+45




5/10

CELL 21
250 - 300 ft

1231+45

1231+95




6/10

CELL 21
300 - 350 ft

1231+95

1232+45




7/10

CELL 21
350 - 400 ft

1232+45

1232+95

Ravel on fog W to S




8/10

CELL 21
400 - 450 ft

1232+95

1233+45




9/10

CELL 21
450 - 500 ft

1233+45

~~1233+95~~
F 20MP



10/10