

4/2/2014 DAV

Ward 9/24/2013 BAT

File ML29 (Previous survey 9/24/2012)


CELL 22
0 - 50 ft

10/27/2014 DAV

1/10

1234+75

1235+25




CELL 22
50 - 100 ft

2/10

1235+25

1235+75




CELL 22
100 - 150 ft

3/10

1235+75

1236+25




CELL 22
150 - 200 ft

4/10

1236+25

1236+75




CELL 22
200 - 250 ft

5/10

1236+75

1237+25




CELL 22
250 - 300 ft

6/10

1237+25

1237+75




CELL 22
300 - 350 ft

7/10

1237+75

1238+25




CELL 22
350 - 400 ft

B/10

1238+25

1238+75




CELL 22
400 - 450 ft

2/10

1238+75

1239+25



E end

CELL 22
450 - 500 ft

stripping
on new cracks

1239+25

1239+75

