

File ML13
Cell 162

5/6/2014 DAV

CELL 162
0 - 50 ft


1157+87
JT 5075

All joints sealed.


JT 5080

10/27/2014 DAV
MINOR CRACKING
NEAR ACCESS PORTS
IN MANWAY @ JT 5100

1158+37



CELL 162
50 - 100 ft



100 - 150 ft


1158+87

JT 5092

JT 5095

1159+37
JT 5100

JT 5100




CELL 162
150 - 200 ft



1159+37
JT 5101

JT 5105

1159+87



4

200 - 225 ft

1159+87

JT 5110

1160+15

JT 5114

JT 5115

1160+37

