

9/24/13 BAT
(previous survey 9/24/12)

File ML01


CELL 1
0 - 50 ft

5/5/2014 DAV

All FWD points (10-1.5)
are 10 ft too far East

1103+10

1103+60




Evidence of w
cracking @ wp
cracks. see pics.

CELL 1 50 - 100 ft


1103+60

1104+10



CELL 1
100 - 150 ft


Peeling of wire mesh
→ N325



CELL 1 150 - 200 ft

1104+60


1105+10



CELL 1 200 - 250 ft

1105+10


1105+60



CELL 1 250 - 300 ft

1105+60


1106+10



CELL 1
300 - 350 ft

1106+10


1106+60



CELL 1
350 - 400 ft

1106+60


1107+10



Conot E 4' Crack

5/5/2014 DSV


CELL 1
400 - 450 ft



CELL 1
450 - 500 ft

1107+60

1108+10



peeling
UTBWD

R/L