

5/5/2014 DAY

File ML23

1200+65

9/24/2013 BAT
(Previous Survey 9/24/2012)
5-12-2015 BJB


CELL 16
0 - 50 ft

Concrt sidewalk
16-8"

10/27/2014 DAY

NO New DISPLESS
OBSERVED.

1201+15



1.5


1201+700

2

CELL 16
50 - 100 ft

1201+15


1201+65



CELL 16
100 - 150 ft


1201+65

1202+15



CELL 16
150 - 200 ft

CONST. SHDR JT.
CRACKING




CELL 16
200 - 250 ft

CONST SHLDR JT
CRACKING

1202+65

1203+15



5

6

5


CELL 16
250 - 300 ft

1203+15

1203+65

rauling
66 sq

CONST SHOULDER
JT. CRACKING



0

7

6


CELL 16
300 - 350 ft

CONST SHLDR
5 ft. CRACKING
6-8" from edge

1203+65

1204+15

FWD 8



7

Fig 16-104


8

7

CELL 16
350 - 400 ft

1204+15

1204+65



8

8

1205+15

19

50'

hole 1x5"

402E

FWD 10

5

1205+15

CELL 16
450 - 500 ft

1205+15

1205+65

