

10/21/2014 DAV

note - cell chip sealed on 7/16/2014.

Wend
File ML26

B.B. 5-12-2015


CELL 19
0 - 50 ft

Snow Plow Scrape caused loss of chip seal
midlane 4'-6'

10/8/2015 LEP

1217+55


1218+05



CELL 19
50 - 100 ft

1218+05


1218+55



CELL 19
100 - 150 ft

1218+55


1219+05



CELL 19
150 - 200 ft

1219+05

1219+55




CELL 19
200 - 250 ft

1219+55

1220+05

1220+00




CELL 19
250 - 300 ft

1220+05

1220+55


FWPS



CELL 19
300 - 350 ft

1220+55


1221+05



CELL 19
350 - 400 ft

1221+05


1221+55



CELL 19
400 - 450 ft

1221+55

1222+05



CELL 19
450 - 500 ft

End
1222+55

1222+05

