

4/2/2014 DAV

Wend

File ML29

1234+75

9/24/2013 BAT

(Previous survey 9/24/2012)


5/11/2015 BJB

CELL 22
0 - 50 ft

10/27/2014 DAV

10/7/2015 BW & DV

1235+25




2/10

CELL 22
50 - 100 ft

1235+25

1235+75




3/10

CELL 22
100 - 150 ft

1236+00

1235+75

1236+25




4/10

CELL 22
150' - 200 ft

1236+25

1236+75



FATIGUE CRACKING

5/10

CELL 22
200 - 250 ft

1237+00

JT M

1/4" - 1"

1236+75

1237+25

0'

10'

20'

30'

40'

50'




6/10

CELL 22
250 - 300 ft

-1237+50

1237+25

1237+75




7/10

CELL 22
300 - 350 ft

1237+75

1238+25




B/10

CELL 22
350 - 400 ft

1238+50

1238+25

1238+75




9/10

CELL 22
400 - 450 ft

1239+00

1239+25
10 FWD

1238+75



Emp

1239+25

staying
on new cracks

1239+75

