


3/20/2014 DAY
5/27/2015 BAB

File LV07

CELL 27
0 - 50 ft

relative to highway section
drawn not drawn

no significant distresses except rutting
used lane 5-6' from E
Plow Scrapes at 40' 1' from fogline
May 2015
scrapes at E
175+80
20
50'




Scrape 3-5" E. Drawn?

CELL 27
50 - 100 ft

175+80

176+30



Spring 2015 Outside lane chip seal - good condition


FWD

CELL 27
100 - 150 ft

Plow scrapes throughout Inside Lane

176+30
FWD 4

176+30
FWD 3



CELL 27
150 - 200 ft


176+80

FWD

Scrape 6'-5"
Flow Center
1' from edge

177+30

FWD




CELL 27
200 - 250 ft

177+50

177+30

177+80

DO
FNG




CELL 27
250 - 300 ft

177+80

178+30

7




6

Plow Scraped

7307


FWD




Plow
Scrap⁴

CELL 27
350 - 400 ft

00+621



CELL 27
400 - 450 ft



CELL 27
450 - 500 ft

