

3/20/2014 DAY
5/27/2015 BVB

11/5/2015
LDR

File LV07

CELL 27
0 - 50 ft

relative to info
drawn - not
drawn

no significant distresses
except rutting

May 2015

scrapes at E

used lane


Flow Scrapes 5-6' from E

Flow Scrapes at 40' 1' from fogline

175+80

N

50'




CELL 27
50 - 100 ft

175+80

176+30

PLow SCRAPE

FWD 50'



Spring 2015 Outside Lane chip seal - good condition

FWD 50'

CELL 27
100 - 150 ft


Plow scraper throughout Inside Lane

176+30


FWD 3

176+80

FWD 4



CELL 27
150 - 200 ft




CELL 27
200 - 250 ft

177+50

177+30

177+80

END




CELL 27
250 - 300 ft

177+80

178+30

7



2

CELL 27
300 - 350 ft

178+30

FWD

0'

plow
scrape

10'

20'

30'

40'

50'

178+80

FWD

12' Inside Lane

8'

CL

4'

8'

12' Outside Lane

0

10'

20'

30'

40'

50'

FATIGUE CRACKING

plow
scrape

Tiny cracks 4"-5"
every 1-2' of 38

CELL 27
350 - 400 ft


179+00

178+80

179+30

8

9



CELL 27
400 - 450 ft

