

9/24/2013 BAT

(Previous Survey 10/2/2012)

File ML18
Cell 73
Ultimate Grind

CELLS 73 & 72
0 - 50 ft

5/8/2014 DAV

10/27/2014 DAV

5/13/2015 BJB

10/07/2015 CEH

1171+54
JT 4269


JT 4270

its unsealed.


JT 4271

JT 4272


1172+04



CELL 73
50 - 100 ft




CELL 73
100 - 150 ft



CELL 73
150 - 200 ft

HS not needed



5-13-2015 BJB

CELLS 73 & 72
200 - 250 ft

5/6/2014

Cell 73 Cell 72
Ultimate Grind Exposed Aggregate
1173+62
JT 4283

it's unsealed

1173+54

5-13-2015
Surface treatment
80% gone
less of fines, oxidation


10/22/2014

DAN

NO NEW JT 4285

DISCREPANCY

1174+04




CELL 72
250 - 300 ft

1174+04
JT 4289


JT 4288

JT 4287

1174+04
JT 4286




CELL 72
300 - 350 ft



Surface wear
loss of treatment layer

CELL 72
350 - 400 ft



CELL 72
400 - 450 ft

1176+00


1175+54

JT 4296


JT 4297

JT 4298

1176+04
JT 4299



CELL 72
450 - 500 ft



5-2015
Surface
have back
fine back

CELL 72
500 - 550 ft

1176+54


1176+62
JT 4303

JT 4304


JT 4305

1177+04

1177+00



CELL 72
550 - 600 ft



CELL 72
600 - 650 ft

1177+54

JT 4310

10'

20'

30'


40'

50'

JT 4311

JT 4312

1178+04



5-2015
OXIDATION
LOSS
of
Surface

CELL 72
650 - 700 ft

Cell 72 Cell 12

1178+04

JT 4313

1178+35
JT 4314

1178+54

