

5/5/2014 DAY

File ML23

1200+65

9/24/2013 BAT
(Previous survey 9/24/2012)
5-12-2015 BJB

CELL 16
0 - 50 ft


Corral shldn't
be here

10/27/2014 DAY

NO NEW SPRINGS
OBSERVED.

10/7/2015 LEP
2/23/16 RCP

1201+15



CELL 16
100 - 150 ft


1201+65

1202+15

4-611

Const. Shld. H. ending

1202




1202+65

CELL 16
200 - 250 ft

CONST SHLDR JT
CRACKING

1203+15




CELL 16
300 - 350 ft

CONST SHLDR
JT. CRACKING.
6-8" from edge

1204+15.

FWD 8.



Fatigue
cracking

7

منتهی

CELL 16
400 - 450 ft

1204+65

2

9.

12' Driving Lane

10

20

2

3

1205+15

61

1205+00

F	465F
---	------

73

FF-2385

什

25

5x1 70/14

9/2/20

12' Passing Lane

10

$$\frac{1}{2}$$

30

4

61

✓ 2308 R

10-11-19

5