

File ML16

9/24/2013 BT
(Previous Survey 9/24/2012)

CELL 70
0 - 50 ft

5/13/2015 BVB

10/27/2014 DAV

10/6/2015 LEP
5/16/2016


1164+14
JT 4219

JT 4220

JT 4221

JT 4222

1164+64



Reflection Cracking

Note: PATCH WAS NOT FROM DISTRESS.
HMA REMOVED FOR STUDY.

CELL 70
150 - 200 ft


1165+64

JT 4230

JT 4231

JT 4232

1166+14




CELL 70
250 - 300 ft

1166+64 JT 4236

JT 4237

JT 4238

1167+14 JT 4239



6

CELL 70
350 - 400 ft

1167-F:64


JT 4243

JT 4244

JT 4245

1168+14

1168 + 00




JT 4250

Cell 70 | Cell 71
1168+83
.JT 4251

CELL 70
450 - 500 ft

1169+00

11.69+14



Crack
on fogline
Sealed
To
JT 4242

Seals

Seal

21.