

9/24/2013 BAT

(Previous Survey 10/2/2012)

CELLS 73 & 72
0-50 ft

5/18/2014 DAV

ITS UNSEALED.

10/27/2014 DAV

5/13/2015 BVB

10/09/2015 CCH

5/17/2016 LCP

4/25/2017 LCP

File ML18
Cell 73
Ultimate Grind


1171+54
JT 4269

JT 4270

JT 4271

JT 4272

1172+04




CELL 73
100 - 150 ft

1172+54
JT 4276

JT 4277

JT 4278

1173+04
JT 4279



STANDARD IS
GRAD 15
ROLLSH 106

5-13-2015 RJB

5/6/2014

its unsealed

CELLS 73 & 72
200 - 250 ft

10/22/2014

DAV

NO NEW JT 4285

DISAPPEARED

5-13-2015
Surface treatment
80% gone
loss of fines, oxidation


1173+54

Cell73/Cell72
Ultimate Grind Exposed Aggregate

1173+62
JT 4283

JT 4284

1174+04



STP
LOADING
TEXTURE

5/1

CELL 72
300 - 350 ft

JT 4291


JT 4292

1175+04

Panel
20

FWD
21 ..

P 23



Surface wear
loss of treatment layer

CELL 72
400 - 450 ft


1175+54
JT 4296

JT 4297

JT 4298

1176+00

1176+04
JT 4299



CELL 72
500 - 550 ft

1176÷54

1176+62
JT 4303


JT 4304

JT-4305

1177+04

FWK
28

1177 ÷ 00



CELL 72
600 - 650 ft


1177+54

JT 4310

JT 4311

JT 4312

1178+04



5-2015
OXIDATION
at
Loss
of fine
soil
surface