

3/20/2017 LEP


11/07/17 LP n/c


3/14/18 MCV

3/12/2018 LEP

8/23/18 MCV

Long const. joints are higher in this cell but crack still visible where drawn





N

Cell 19, 100 Feet - 150 Feet

Station
1218+55

10-Foot Shoulder

HMA Cracking Study

0'


10'

20'

30'

40'

50'



4-Foot Shoulder

Not found 8/23/18

N

Cell 19, 150 Feet - 200 Feet

Station
1219+05

10-Foot Shoulder

HMA Cracking Study

0'

10'

20'

30'

40'

5'



4-Foot Shoulder

N

Cell 19, 200 Feet - 250 Feet

Station
1219+55

10-Foot Shoulder

HMA Gracking Study

0'


10'

20'

30'

40'

50'



4-Foot Shoulder

N

Cell 19, 250 Feet - 300 Feet

Station
1220+05

10-Foot Shoulder

HMA Cracking Study

0'

10'

20'

30'

40'

50'

0

10

20

30

40

50

60

70

80

90

100

110

120

130

0

tight
CL
& back

4-Foot Shoulder

N

Cell 19, 300 Feet - 350 Feet

Station
1220+55

10-Foot Shoulder

HMA Cracking Study

0'


10'

20'

30'

40'

50'



4-Foot Shoulder

N

Cell 19, 350 Feet - 400 Feet

Station
1221+05

10-Foot Shoulder

HMA Cracking Study

50'

40'

30'

20'

10'

0'

0



4-Foot Shoulder

N

Cell 19, 400 Feet - 450 Feet

Station
1221+55

10-Foot Shoulder

HMA Cracking Study

0'

10'

20'

30'

40'

50'

7200



4-Foot Shoulder

N

Cell 19, 450 Feet - 500 Feet

End Station is
1222+55

Station
1222+05

10-Foot Shoulder

HMA Cracking Study

0'

10'

20'

30'

40'

50'

right



0 0 0 0

0 0 0 0

0 0 0 0

0 0 0

0 0 0

0 0 0

4-Foot Shoulder