

3/20/17 LEP
0/7/2012 d


n/c

3/15/18

4/27/18 mcl MCV
8/23/18 MCV/LEP

8/23
Not visible
throughout No
crack @ bottom
of gauge

Drag line/gauge in LWP on
driving lane throughout cell
↳ Not cracked under gauge



N

Cell 23, 50 Feet - 100 Feet

Station
1241+05

10-Foot Shoulder

HMA Cracking Study

0'


10'

20'

30'

40'

50'



4-Foot Shoulder

N

Cell 23, 100 Feet - 150 Feet

Station
1241+55

10-Foot Shoulder

HMA Cracking Study

0'

10'

20'

30'

40'

50'

drag

drag

4-Foot Shoulder

N

Cell 23, 150 Feet - 200 Feet

Station
1242+05

10-Foot Shoulder

HMA Gracking Study

0'


10'

20'

30'

40'

5'



Grack

Grack

4-Foot Shoulder

N

Cell 23, 200 Feet - 250 Feet

Station
1242+55

10-Foot Shoulder

HMA Cracking Study

0'

10'

20'

30'

40'

50'

Low
2nd
Main

6/8/17

Box

4-Foot Shoulder

N

Cell 23, 250 Feet - 300 Feet

Station
1243+05

HMA Gracking Study

10-Foot Shoulder

0'


10'

20'

30'

40'

50'



drag

drag

low
seal
low

4-Foot Shoulder

N

Cell 23, 300 Feet - 350 Feet

Station
1243+55

10-Foot Shoulder

HMA Gracking Study

Low
Long

0'

10'

20'

30'

40'

50'

- gauge

po

gouges

drag

po

4-Foot Shoulder

N

Cell 23, 350 Feet - 400 Feet

Station
1244+05

10-Foot Shoulder

HMA Cracking Study

0'

10'

20'

30'

40'

50'

1 1/4"
Deep
Gaps

drag

Ravel
C/C
JOINT

Ravel
C/C
JOINT

4-Foot Shoulder

N

Cell 23, 400 Feet - 450 Feet

Station
1244+55

10-Foot Shoulder

HMA Cracking Study

0'


10'

20'

30'

40'

50'



drag

drag

4-Foot Shoulder

N

End Station is
1245+55

Cell 23, 450 Feet - 500 Feet

Station
1245+05

10-Foot Shoulder

HMA Cracking Study

0'

10'

20'

30'

40'

50'

CR

Big
D.P. 14
REPRODUCTION
FALL 2006

P₀

P₀

Patch

CR

CR

4-Foot Shoulder