


1/12/18
3/20/18
3/19/2018
N/C

3/14/18
4/22/18
MCV
8/23/2018
KCP

Appears. raveling & stripping beginning throughout
3/22/19
4/16/19
MCV





Station
1235+80

Cell 22, 100 Feet - 150 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'

20'

30'

40'

50'

N



4-Foot Shoulder

Station
1236+30

Cell 22, 150 Feet - 200 Feet

HMA Gracking Study

10-Foot Shoulder

N

0'

10'

20'

30'

40'

50'

Grack

#12

4-Foot Shoulder

Station
1236+80

Cell 22, 200 Feet - 250 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'

20'

30'

40'

50'

N

Shoulder

SHOULDER CRACKS SUBSISTENT TO CRACK

4-Foot Shoulder

Station
1237+30

Cell 22, 250 Feet - 300 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'

20'

30'

40'

50'

4/17/14
22-2
Core location

N

RUBBLE TIDE ROCK CRACK

10-foot

4-Foot Shoulder

Station
1237+80



Cell 22, 300 Feet - 350 Feet

HMA Cracking Study

0'


10'

20'

30'

40'

50'



Rubberized Rutting BAR



4-Foot Shoulder

10-Foot Shoulder

Station
1238+30

Cell 22, 350 Feet - 400 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'


20'

30'

40'

50'

N



4-Foot Shoulder

Station
1238+80



Cell 22, 400 Feet - 450 Feet

HMA Cracking Study

0'


10'

20'


30'

40'

50'



1/2" x 3/4" x 1/2" RUCR, CRAP



4-Foot Shoulder

10-Foot Shoulder

Station
1239+30

Cell 22, 450 Feet - 500 Feet

HMA Cracking Study

End Station is
1239+80
10-Foot Shoulder

N

0'

10'

20'

30'

40'

50'



Grass



1.6

MAR 8/80

12



4-Foot Shoulder