

1/12/18
3/20/18
3/14/18
N/C

3/14/18 MCV
4/23/18 MCV
8/23/2018 KCP

Appears. raveling & stripping beginning throughout
3/22/19 MCV
4/16/19 MCV
10/23/19 MCV - All CLIC on driveway - Joint Sealed





Station
1238+30

Cell 22, 50 Feet - 100 Feet

HMA Cracking Study

0'

20-1-
10' 4/17/19
Con Location

20'

30'

40'

50'

sealed

ONS
MVP

LC

RC

RC

RC

sealed


LC
MVP

0



4-Foot Shoulder

10-Foot Shoulder



Station
1235+80

Cell 22, 100 Feet - 150 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'


20'

30'

40'

50'


Sealed



Long Nurb



Sealed



4-Foot Shoulder

Station
1236+30

Cell 22, 150 Feet - 200 Feet

HMA Cracking Study

10-Foot Shoulder

N

0'

10'

20'

30'

40'

50'

Bridge

Sealed

Sealed

4-Foot Shoulder

Station
1236÷80

Cell 22, 200 Feet - 250 Feet

HMA Cracking Study

10-Foot Shoulder

Seal

Sales

4-Foot Shoulder

Station
1237+30

Cell 22, 250 Feet - 300 Feet

HMA Cracking Study

10-Foot Shoulder

N

0'

10'

20'

30'

40'

50'

H/IR-114

CR-2

Sealed

Sealed

Rubber tire roller draft

4-Foot Shoulder

Station
1237+80

Cell 22, 300 Feet - 350 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'

20'

30'

40'

50'

N


sealed

sealed

growing

Keeper 1120 Rutting BAR

4-Foot Shoulder





Station
1288+30

Cell 22, 350 Feet - 400 Feet


HMA Cracking Study

10-foot Shoulder

0' 10' 20' 30' 40' 50'

Sealed

4-Foot Shoulder



Station
1238+80



Cell 22, 400 Feet - 450 Feet

HMA Cracking Study

0'

10'

20'

30'


40'

50'

10-Foot Shoulder

Sealed

1/2" x 3/4" x 6" Rebar



4-Foot Shoulder

Station
1239+30

Cell 22, 450 Feet - 500 Feet

HMA Cracking Study

10-Foot Shoulder

End Station is
1239+80

N

0'

10'

20'

30'

40'

50'

sealed

groove

sealed

1.1.1

MARS 3480

15.2

4-Foot Shoulder: