


3/20/17 LCB
0/1/2012 48

n/c

3/15/18

4/27/18 MCV MCV
8/23/18 MCV/LP

3/22/2019 MCV



Station
1241+05

Cell 23, 50 Feet - 100 Feet

HMA Cracking Study

10-Foot Shoulder

N

0'


10'

20'

30'


40'

50'



4-Foot Shoulder

Station
1241+55



Cell 23, 100 Feet - 150 Feet

HMA Cracking Study

10-Foot Shoulder

0' 10' 20' 30' 40' 50'

dry

dry

4-Foot Shoulder

Station
1242+05

Cell 23, 150 Feet - 200 Feet

HMA Cracking Study

10-Foot Shoulder

0' 10' 20' 30' 40' 50'

N

Survey

Survey

4-Foot Shoulder

Station
1242+55

Cell 23, 200 Feet - 250 Feet

HMA Cracking Study

10-Foot Shoulder

N

0'

10'

20'

30'

40'

50'

Low
Spall

5' x 13'

1/2" gap

4-Foot Shoulder

Station
1243+05

Cell 23, 250 Feet - 300 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'

20'

30'

40'

50'

N

1/2"

1/2"

4-Foot Shoulder

Station
1243+55

Cell 23, 300 Feet - 350 Feet

HMA Cracking Study

10-Foot Shoulder

0'

10'

20'

30'

40'

50'

N

Flag

EL 906.05

gauge

pp

Low
Low

4-Foot Shoulder

HMA Cracking Study

1. Dec 1993

Page 8 of 10

Station
124+55

Cell 23, 400 Feet - 450 Feet

HMA Cracking Study

10-Foot Shoulder

4-Foot Shoulder

N

0'

10'

20'

30'

40'

50'

Crack
Width

Gravel

Gravel

Station
1245+05

Cell 23, 450 Feet - 500 Feet

HMA Cracking Study

End Station is
1245+55
10-Foot Shoulder

N

0'

10'

20'

30'

40'

50'

(R-1)

(R-5)

4-Foot Shoulder